

L Number	Hits	Search Text	DB	Time stamp
1	35	"3R regenerator"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:23
2	18	"3R regenerator" and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:23
3	12	("3R regenerator" and clock) and delay	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 13:06
4	0	rehenerat\$4 same clock same (delay adj interference)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:35
5	5	regenerat\$4 same clock same (delay adj interference)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 10:35
6	6	("5781326"   "5940207"   "5959764"   "6259552"   "6335819"   "6377388").PN.	USPAT	2003/08/19 10:50
7	3	6335819.URPN.	USPAT	2003/08/19 10:53
8	8	("5532861"   "5726787"   "5959764"   "5974209"   "6101027"   "6108125"   "6124966"   "6215566").PN.	USPAT	2003/08/19 10:57
9	4	("5761228"   "5796765"   "5799024"   "5844932").PN.	USPAT	2003/08/19 11:02
10	1	6124966.URPN.	USPAT	2003/08/19 11:53
11	10	6108125.URPN.	USPAT	2003/08/19 11:57
12	5	("5401957"   "5548433"   "5717510"   "5757529"   "5892608").PN.	USPAT	2003/08/19 11:57
13	8	("5532861"   "5726787"   "5959764"   "5974209"   "6101027"   "6108125"   "6124966"   "6215566").PN.	USPAT	2003/08/19 12:04
14	3	6335819.URPN.	USPAT	2003/08/19 12:04
15	6	("5111326"   "5267073"   "5619368"   "5625479"   "5828484"   "5960146").PN.	USPAT	2003/08/19 12:10
16	1	6259552.URPN.	USPAT	2003/08/19 12:11
17	7	5781326.URPN.	USPAT	2003/08/19 12:14
18	3	6229633.URPN.	USPAT	2003/08/19 12:32
19	19	("4881788"   "5150248"   "5369520"   "5369522"   "5379143"   "5434692"   "5444560"   "5446573"   "5450229"   "5504610"   "5515199"   "5546190"   "5548433"   "5574588"   "5644665"   "5774246"   "5781326"   "5822103"   "6067180").PN.	USPAT	2003/08/19 12:33
20	9	5574588.URPN.	USPAT	2003/08/19 12:40
21	1	"5457559".PN.	USPAT	2003/08/19 12:46
22	13	5457559.URPN.	USPAT	2003/08/19 12:48
23	19	("4881788"   "5150248"   "5369520"   "5369522"   "5379143"   "5434692"   "5444560"   "5446573"   "5450229"   "5504610"   "5515199"   "5546190"   "5548433"   "5574588"   "5644665"   "5774246"   "5781326"   "5822103"   "6067180").PN.	USPAT	2003/08/19 12:55
24	3	6229633.URPN.	USPAT	2003/08/19 12:55
25	116	359/176 and delay	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 13:06
26	71	(359/176 and delay) and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 15:20

27	13	("5237290"   "5416769"   "5469284"   "5486943"   "5734486"   "5737106"   "5757872"   "5831752"   "5999293"   "6067180"   "6091524"   "6282007"   "6373608").PN.	USPAT	2003/08/19 13:53
28	3	("5401957"   "5594583"   "5625636").PN.	USPAT	2003/08/19 14:33
29	5	5401957.URPN.	USPAT	2003/08/19 14:34
30	2	5861971.URPN.	USPAT	2003/08/19 14:35
31	4	5764396.URPN.	USPAT	2003/08/19 14:45
32	8	("4350879"   "4561101"   "5369520"   "5392147"   "5459607"   "5493433"   "5548433"   "5646759").PN.	USPAT	2003/08/19 14:46
33	135	359/176 and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 15:33
34	113	"optical regenerator" and clock	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/19 15:34
35	11	("4313224"   "5107483"   "5410624"   "5483372"   "5532863"   "5539557"   "5576883"   "5689594"   "5777766"   "5801862"   "5838475").PN.	USPAT	2003/08/19 15:39
36	15	4980891.URPN.	USPAT	2003/08/19 15:48